

Cal Dining Eateries (Martin Luther King, Jr. Building - 1st floor)

UCB Follow-Up Inspection - Food

Current Managers

Andrew Fan, Jason Maddy, Laquetta Riley,
Sunil Chacko

Inspection Date

Sep 11, 2023

Status

Inspection Contributors

Muzna Rauf

Inspection Resolvers

-

Notes

Follow-up inspection was conducted on 09/08/23 to check for compliance of violation #21(a) as observed on inspection report dated 09/01/23. Hot water temperature at the 3-compartment warewash sink was recorded at 116 degrees F. As per the plumber, keeping the taps open overnight is causing the water temperature to drop. Staff shut down sink for use on 9/08/23. There is a second 3-compartment warewash sink in the facility that has hot water of 120 degrees and above available. Hot water temperature was checked again on 9/11/23. Hot water temperature was recorded above 120 degrees F at the 3-compartment warewash sink. Staff instructed to resume using sink for warewashing purposes. Violation #21(a) has been abated. Any pending non-critical violations will be checked at next routine inspection.

– Muzna Rauf

Observations and Corrective Actions *

Observations and Corrective Actions

Public Comments: Violation #21(a) for no hot water at the warewashing sink has been corrected with reasonable compliance. Hot water temperature measured at 120 degrees F and greater at the warewashing sink at the time of the re-inspection.

Inspector: Muzna Rauf

Status: Compliant