

Cal Dining Eateries (Martin Luther King, Jr. Building - 1st floor)

UCB Follow-Up Inspection - Food

Current Managers

Andrew Fan, Jason Maddy, Laquetta Riley,
Sunil Chacko

Inspection Date

Oct 4, 2023

Inspection Contributors

Muzna Rauf

Inspection Resolvers

-

Notes

A follow-up inspection was conducted to check for compliance of violations observed on complaint report dated 09/21/2023.

All violations have been abated. Exhaust fan belt has been replaced, and hood is functioning properly. Monsoon Kitchen to resume operations under hood located at MLK 112.

— Muzna Rauf

Observations and Corrective Actions *

Observations and Corrective Actions

Public Comments: 1) Violation for accumulation of grease and dust on the fire suppression lines above the grill has been corrected with reasonable compliance.
2) Violation for accumulation of grease and dust on the surface of the hood and filters has been corrected with reasonable compliance.
3) Grease exhaust hood cleaned and serviced by AAA on 10/04/2023. Ensure hood is serviced every 6 months or sooner if needed.

Inspector: Muzna Rauf

Status: Compliant